



Maintenance Work on Sherburne Reservoir







St. Mary Diversion Dam



St. Mary Siphon





2003 leak in St. Mary Siphon where pipe crosses the St. Mary River



in collar joints of St. Mary Siphon

Leaks



Section of buckled siphon replaced in 2003





Pipe repair work in 2003



Hall's Coulee Siphon



View of Drop No 4 looking upstream



Eroded concrete and exposed rebar in face of drop structure